

# AHERA - ASBESTOS RE-INSPECTION OF ACM & PACM

**MATUNUCK ELEMENTARY SCHOOL**  
SOUTH KINGSTON SCHOOL DEPARTMENT

REINSPECTION DATE: FEBRUARY 28, 2018

		INSPECTION FINDINGS FOR ACM/PACM							Response Action						Initials of Surveillance Inspector					
		Type and Quantity																		
		FLOOR COVERING (NF)				CEILING TYPE (F)														
Location of ACBM	Floor	12" FL. TILE ONLY	RUBBER	ceramic	PACM FITTINGS	PLASTER	2' X 2'	Wall Material	ACM	FRIABLE	DAMAGED	PHYSICAL ACCESS.	HAZARD ASSESS.	RESPONSE	Comments / Notes	6 MONTH SURVEILLANCES				
		MISC.		MISC.	TSI		SURFACE	SURFACE								8/18	2/19	8/19	2/20	8/20
<b>HOMOGENEOUS AREA</b>																				
MAIN OFFICE	1	1675					1675	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
BOILER ROOM	1				40			BL	Y	N	N	5	2	T7	REPAIR 3 FITTINGS	REPAIRED	N/C	N/C		
STORAGE @ ENTRY	1	450					450	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
MAIN HALL	1	1000					1000	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
HALLWAY	1	800					800	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
CAFETERIA	1	2600					2600	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
KITCHEN	1			550				BL	A	N	N	5	2	M8		N/C	N/C	N/C		
GYM	1		2400					BL	A	N	N	5	2	M8		N/C	N/C	N/C		
STAGE	1							BL	A	N	N	5	2	M8		N/C	N/C	N/C		
CUSTODIAN	1				2			BL	Y	N	N	5	2	T7		N/C	N/C	N/C		
MECHANICAL RM	1				30			BL	Y	N	N	5	2	T7		N/C	N/C	N/C		
CLOSET	1	180					180	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
WORKROOM	1						400	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
FACULTY ROOM	1	400					400	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
BR 1	1			120				BL	A	N	N	5	2	M8		N/C	N/C	N/C		
BR2	1			120				BL	A	N	N	5	2	M8		N/C	N/C	N/C		
CONFERENCE	1	400					400	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
NURSE	1	NON ACM					300	BL	A	N	N	5	2	M8	VAT ABATED IN 6/04, MASTIC NEG.					
BR	1			80			80	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
PRINC. OFFICE	1	400					400	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
BR I	1			240			240	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
BR2	1			240			240	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
HALLWAY	1	400					400	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
OFFICE	1	120					120	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
STORAGE	1	400					400	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
SUPPLY ROOM	1	400					400	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
BR 1	1			120				BL	A	N	N	5	2	M8		N/C	N/C	N/C		
							120	BL	A	N	N	5	2	M8		N/C	N/C	N/C		

INSPECTION FINDINGS FOR ACM/PACM															Initials of Surveillance Inspector					
Type and Quantity															John Carbone	John Carbone	John Carbone			
FLOOR COVERING (NF)      CEILING TYPE (F)															6 MONTH SURVEILLANCES					
Location of ACBM	Floor	12" FL. TILE ONLY	CARPET OVER TILE	ceramic		PLASTER	2' X 2'	Wall Material	Response Action					Comments / Notes	8/18	2/19	8/19	2/20	8/20	
									ACM	FRIABLE	DAMAGED	PHYSICAL ACCESS.	HAZARD ASSESS.							RESPONSE
BR 2	1			120				BL	A	N	N	5	2	M8		N/C	N/C	N/C		
						120		BL	A	N	N	5	2	S8		N/C	N/C	N/C		
MEDIA CENTER	1							BL	A	N	N	5	2	M8		N/C	N/C	N/C		
SPEECH OFFICE	1	144					144	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
READING	1	200					200	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
STORAGE	1	400					400	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
HALLWAY	1	720					720	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
HALLWAY	1	1300					1300	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
CLASSROOM 109	1	400					400	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
110	1	400					400	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
101 LIBRARY & 111-118		NON ACM						BL	N						VAT ABATED IN 6/02, MASTIC NEG.					
119	1	950					950	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
120A	1	400					400	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
120B	1	400					400	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
121	1	950					950	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
122	1	950					950	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
123	1	950					950	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
124	1	950					950	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
125	1	950					950	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
126	1	950					950	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
137A & 137B	1	950					950	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
128	1		950				950	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
129	1		950				950	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
130	1	950					950	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
131	1	950					950	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
THROUGHOUT BLDG - ABOVE CEILINGS					50 TSI FITTINGS				Y	N	N	5	2	T8		N/C	N/C	N/C		
THROUGHOUT - DOOR CORE					100+				Y	N	N	5	2	M8		N/C	N/C	N/C		

Code: N = NO; Y = YES; T = THERMAL; S = SURFACING; M = MISCELLANEOUS  
 N/C = NO CHANGE; R = REPAIRED; D = DAMAGED

**FLOOR TILE & MASTIC (1975 BUILDING): Only the 12" square floor tile (beige/brown color) and mastic within the original building contains asbestos.**