

# AHERA - ASBESTOS RE-INSPECTION OF ACM & PACM

## WEST KINGSTON ES

## SOUTH KINGSTON SCHOOL DEPARTMENT

REINSPECTION DATE: FEBRUARY 28, 2018

INSPECTION FINDINGS FOR ACM/PACM															Initials of Surveillance Inspector					
Type and Quantity																				
		FLOOR COVERING (NF)				ACM FITTINGS	CEILING TYPE (F)			Response Action										
Location of ACBM	Floor	12" FL. TILE ONLY	CARPET OVER TILE	ceramic	PLASTER		2' X 2'	Wall Material	ACM	FRIABLE	DAMAGED	PHYSICAL ACCESS.	HAZARD ASSESS.	RESPONSE	Comments / Notes	6 MONTH SURVEILLANCES				
		MISC.	MISC.	MISC.	TSI	SURFACE	MISC.	MISC.							8/18	2/19	8/19	2/20	8/20	
<b>HOMOGENEOUS AREA</b>		<b>NEW</b>					1675	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
MAIN OFFICE	1							BL	Y	N	N	5	2	T7	REPAIR 3 FITTINGS	REPAIRED	N/C	N/C		
MECH. RM /B.R.	1				30			BL												
STORAGE	1	450					450	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
MAIN HALL	1	1000					1000	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
HALLWAY	1	800					800	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
CAFETERIA	1	2600						BL	A	N	N	5	2	M8		N/C	N/C	N/C		
KITCHEN	1							BL	A	N	N	5	2	M8		N/C	N/C	N/C		
GYM	1							BL	A	N	N	5	2	M8		N/C	N/C	N/C		
STAGE	1							BL	A	N	N	5	2	M8		N/C	N/C	N/C		
CUSTODIAN	1				3			BL	Y	N	N	5	2	T7		N/C	N/C	N/C		
ELECTRICAL	1							BL	A	N	N	5	2	M8		N/C	N/C	N/C		
CLOSET	1	180					180	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
WORKROOM	1		400				400	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
FACULTY ROOM	1		400				400	BL	A	N	N	5	2	M8	CARPET OVER TILE	N/C	N/C	N/C		
BR 1	1						140	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
BR2	1						140	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
CONFERENCE	1	400					400	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
NURSE	1						400	BL	A	N	N	5	2	M8	NEW VCT	N/C	N/C	N/C		
BR	1			80			80	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
PRINC. OFFICE	1						400	BL	A	N	N	5	2	M8	NEW VCT	N/C	N/C	N/C		
BR I	1						240	BL	A	N	N	5	2	M8	NEW VCT	N/C	N/C	N/C		
BR2	1						240	BL	A	N	N	5	2	M8	NEW VCT	N/C	N/C	N/C		
HALLWAY	1	400					400	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
OFFICE	1	120					120	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
STORAGE	1	400					400	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
SUPPLY ROOM	1	400					400	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
BR 1	1			120		120		BL	A	N	N	5	2	M8		N/C	N/C	N/C		
BR 2	1			120		120		BL	A	N	N	5	2	M8		N/C	N/C	N/C		
MEDIA CENTER	1							BL	A	N	N	5	2	M8		N/C	N/C	N/C		

															Initials of Surveillance Inspector					
Type and Quantity															John Carbone	John Carbone	John Carbone			
Location of ACBM	Floor	FLOOR COVERING (NF)				MISC	CEILING TYPE (F)			Response Action					Comments / Notes	6 MONTH SURVEILLANCES				
		12" FL. TILE ONLY	concrete	ceramic			TECNUM CEIL	2' X 2'	Wall Material	ACM	FRIABLE	DAMAGED	PHYSICAL ACCESS.	HAZARD ASSESS.		RESPONSE	8/18	2/19	8/19	2/20
<b>HOMOGENEOUS AREA</b>		MISC.	MISC.	MISC.		MISC	MISC	MISC												
SPEECH OFFICE	1	144					144	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
READING	1	200					200	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
STORAGE	1	400					400	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
HALLWAY	1	720					720	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
HALLWAY	1	1300					1300	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
CLASS 106 - 109	1	3200					3200	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
110	1	400					400	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
101 LIBRARY, 111 118	1	NON ACM						BL	N						VAT ABATED IN 6/02, MASTIC NEG.					
CORRIDOR 119-127		1500					1500	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
119	1	200					900	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
STORAGE ACROSS @119	1	200					200	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
120A	1	400					400	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
120B	1	400					400	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
121	1	200					900	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
122	1	200					900	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
123	1	200					900	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
124	1	200					900	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
125	1	200					900	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
126	1	200					900	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
127	1	200					900	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
137A & 137B	1	400					950	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
129	1	950					950	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
130	1	950					950	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
131	1	950					950	BL	A	N	N	5	2	M8		N/C	N/C	N/C		
132-133	1						500	BL	A	N	N	5	2	M8	NEW VCT					
135	1							BL	A	N	N	5	2	M8		N/C	N/C	N/C		
THROUGHOUT BLDG - ABOVE CEILINGS						50 TSI FITTINGS			A	N	N	5	2	M8		N/C	N/C	N/C		
THROUGHOUT - DOOR CORE						100+			Y	N	N	5	2	M8		N/C	N/C	N/C		

Code: N = NO; Y = YES; T = THERMAL; S = SURFACING; M = MISCELLANEOUS  
 N/C = NO CHANGE; R = REPAIRED; D = DAMAGED

**FLOOR TILE & MASTIC (1975 BUILDING): Only the 12" square floor tile (beige/brown color) and mastic within the original building contains asbestos.**